



Colour Chart 20. Jul 2016	Unleaded Colours for Porcelain and Bone China „Series BA“ Firing Temperature 800°- 900° C	Seite: 1/1
---	---	----------------------

The Colour Chart shows a close impression of the Basis Colours for a first selection. For an exact evaluation of the colour shade it is necessary to test a sample under original conditions. Colour shades depend on layer thickness and firing temperature.

 Mixing White BA 9581 Pant. White	 White BA 9580 Pant. White	 Black BA 4180 Pant. BlackC	 Chromegreen BA 1880 Pant. 7742C	 Bluegreen BA 1881 Pant. 323C	 Light Green BA 1882 Pant. 362C
 Turquoise BA 2586 Pant. 634C	 Blue BA 2581 Pant. 7461C	 Blue BA 2585 Pant. 7684C	 Blue BA 2588 Pant. 7456C	 Red Brown BA 6582 Pant. 7624C	 Lemon Yellow BA 3580 Pant. 393C
 Cd-Yellow BA 3581 Pant. 109C	 Corn Yellow BA 3582 Pant. 137C	 Cd-Orange BA 7580 Pant. 1655C	 Cd-Red BA 7581 Pant. 1795C	 Cd-Red BA 7582 Pant. 186C	 Cd-Darkred BA 7583 Pant. 201C
 Rose BA 7883 Pant. 700C	 Rose BA 7882 Pant. 203C	 Purple Dark PBA 7880 Pant. 7641C	 Purple Red PBA 7881 Pant. 7420C		

Please Note:

The information in this leaflet are based on our current knowledge and experience. This description does not release the users from examinations and tests of their own because of uncountable possible influences, when using and applying the products in connection with every other material being involved in the production. It can not be deduced a legally obliged assurance for specific characteristics or for the aptitude of a definite usage purpose. The receiver of our products has to observe by his own responsibility probable protecting rights as well as existing laws, rules and regulations.

Rüger & Günzel GmbH
Dornhofstrasse 71
D 63263 Neu-Isenburg
Tel: +49(0)6102-812940
Fax: +49(0)6102-8129440
E-Mail: info@rgfarben.de